Automatic Bluetooth connection on the 260DBi motorway

Laura - 2021-10-19 - Highway H260DBI/ H240DI

A small number of users have reported some inconsistencies with the 'auto connect' function on the Highway 260DBi, where their phone is not automatically connecting, after some time, when re-entering the vehicle.

If you experience this a new software update has been released to resolve this. Click here for the software and instructions.