My Contour 200i Air has too much bass

Laura - 2021-10-19 - Docks und Airplay

Check that your Contour 200i Air is running the latest firmware to ensure you experience the best from your product!

A possible cause is that the EQ settings have been changed on your Apple device. Try turning off your EQ settings on your Apple device by selecting **Settings > Music > EQ** and selecting **Off**.