

FAQs > Help by Connection Type (BT, Internet,...) > Autoradio > Highway 300Di > The Highway 300Di is not responsive

The Highway 300Di is not responsive

Laura - 2021-10-19 - Highway 300Di

In the unlikely event that your Highway 300Di becomes unresponsive and appears 'locked up', you can always recover the product by forcing a reboot.

Forcing a reboot:

- Remove your Highway 300Di controller module from the mounting bracket.
- Press and hold down the **Preset** and **Back** buttons on the controller and at the same time insert the controller back into the mounting bracket.
- Let go of the **Preset** and **Back** button when you see the Highway logo appear on the controller screen.

The reboot is complete and you should now have control of your Highway 300Di.