



[FAQs](#) > [Help by Connection Type \(BT, Internet,...\)](#) > [In car radio](#) > [Highway 300Di](#) > [Poor DAB reception with an iPod plugged in on the 300Di motorway](#)

Poor DAB reception with an iPod plugged in on the 300Di motorway

Laura - 2021-10-19 - [Highway 300Di](#)

If you experience poor DAB reception while you have an iPod plugged in to your Highway 300Di (for example to charge it), you should ensure you are using an official Apple iPod accessory cable for your connection.

Unbranded (non-Apple) accessory cables that are not sufficiently shielded may cause radiated RF interference which will degrade your DAB signal.

You can purchase official Apple accessories from <http://store.apple.com/uk>